Declassified in Part - Sanitized Copy Approved for Release 2012/06/04 : CIA-RDP81-00280R000100100002-1

Declassified in Part - Sanitized Copy Approved for Release 2012/06/04 : CIA-RDP81-00280R000100100002-1

LINITED: Dissemination limited to full-time employees of CIA, AEC and FBI; and, within State and Defense, to the intelligence components of the offices producing NIS after the find higher achieves with their immediate supporting statis. It is not disseminated to communitate approaches the producing NIS after the find distribution of the original community of the AEC, FBI from Defense of the AEC, FBI from Defense or the communitate of the AEC, FBI from Defense or the communitate of the AEC, FBI from Defense or the communitate of the AEC, FBI from Defense or the communitate of the AEC, FBI from Defense or the communitate of the AEC, FBI from Defense or the communitate or

	vicinity of position 50.05.00 H and 25-50.00 H there were anchored two Soviet "cruisers" and seven "destroyers". The "cruisers" had a single break in the hull line and the level was broken amidships. There was a prominent spherical gum director forward above the bridge; there were two turrets forward and two aft; there were two stacks; there was a mainmast aft	
	The ships flew the Soviet flag. As to the	
	"destroyers": they were between 350 and 400 feet in length; all were tw stackers; each had one turret forward and one aft; equipment which	В
	appeared to be torpedo tubes could be seen smidships. The bow showed	
	a good rake all ships flew the	50X1-HL
	Soviet flag. While the	
	were anchored there, a small minesweeper conducted sweeping operations	y
	between our ship and the task force.	
[On each	 50X1-HL
	day about 20 motor torpedo boats departed the port on a northwesterly	30/(1-110
	heading and returned at evening. they were engaged in	_50X1-HU
	practice operations.	
	In the area of Winter Harbor	\exists
	number of minesweepers too numerous to count accurately.	
	number of minesweepers too numerous to count accurately.	
	number of minesweepers too numerous to count accurately. there were approximately 40 of them.	
	number of minesweepers too numerous to count accurately. there were approximately 40 of them. it possible that the "cruisers" were "Chapavey" class. and the	
	number of minesweepers too numerous to count accurately. there were approximately 40 of them.	
	number of minesweepers too numerous to count accurately. there were approximately 40 of them. it possible that the "eruisers" were "Chapayev" class, and the "destroyers "either "Skoryy" or Otlichnyy" class.	
	it possible that the "eruisers" were "Chapayev" class, and the "destroyers either Skoryy or Otlichnyy class. Aids to Navigation: The sea buoy (flashing five seconds) has been	
	it possible that the "cruisers" were "Chapayev" class, and the "destroyers" cither "Skoryy or Otlichnyy class] Aids to Navigation: The sea buoy (flashing five seconds) has been moved from approximate position 57-06-30 N and 23-57-00 E to a new	50X1.HI
	it possible that the "eruisers" were "Chapayev" class, and the "destroyers either Skoryy or Otlichnyy class. Aids to Navigation: The sea buoy (flashing five seconds) has been	50X1-HU
	it possible that the "cruisers" were "Chapayev" class, and the destroyers either skoryy or Otlichnyy class. Aids to Navigation: The sea buoy (flashing five seconds) has been moved from approximate position 57-06-30 N and 23-57-00 E to a new position at approximately 57-10-30 N and 23-55-30 E. There used to be	_50X1-HU
	it possible that the "cruisers" were "Chapayev" class, and the destroyers either skoryy or Otlichnyy class. Aids to Navigation: The sea buoy (flashing five seconds) has been moved from approximate position 57-06-30 N and 23-57-00 E to a new position at approximately 57-10-30 N and 23-55-30 E. There used to be	50X1-HU
	it possible that the "cruisers" were "Chapayev" class, and the destroyers either skoryy or Otlichnyy class. Aids to Navigation: The sea buoy (flashing five seconds) has been moved from approximate position 57-06-30 N and 23-57-00 E to a new position at approximately 57-10-30 N and 23-55-30 E. There used to be	50X1-HU
	it possible that the "cruisers" were "Chapayev" class, and the destroyers either skoryy or Otlichnyy class. Aids to Navigation: The sea buoy (flashing five seconds) has been moved from approximate position 57-06-30 N and 23-57-00 E to a new position at approximately 57-10-30 N and 23-55-30 E. There used to be	50X1-HU
	it possible that the "cruisers" were "Chapayev" class, and the destroyers either skoryy or Otlichnyy class. Aids to Navigation: The sea buoy (flashing five seconds) has been moved from approximate position 57-06-30 N and 23-57-00 E to a new position at approximately 57-10-30 N and 23-55-30 E. There used to be	50X1-HU

C=O=N=F=I=D=E=N=T=I=A=L

NOFORM

NO DISSEM ABROAD

LDCERED

- Days before Sundays and Holidays to count as three-quarters of a day, wheth used or not. On Mondays and the days after general or local holidays time not to count until θ a.m., whether used or not.
- Charterers are entitled to work during the excepted periods without counting time, they paying Grew's and Officers! overtime at the rate of 2/6d. per hour to Officers and 2/- per hour to Grew.
- 3. Steemer to supply steem, winches, winchese, guynen, gins, falls, runners and slings during day and night free of expense to Charterers and Charterers to have free use of ship's lighting for night work, if required. Grew to drive winches if willing and permitted by local labour regulations, otherwise shore hands to be employed and Ounces to pay 34. (threepense) per ton on the quantity loaded. In cases whose the winch elemes becomes inoperative by reason of cargo being discharged by shore appliances vessel to pay 34. (threepense) per ton to defray the cost of the use of such shore appliances.
- b. Charterers shall have the bytica of discharging at two safe berths in one part without extra freight and time for shifting not to count. Further shiftings to be for Charterers' assessed and time for shifting to count.
- 5. Any time lost by reason of breakdown of winches and/or desticks to be deducted from the laytime.
- fo. Chytain must give seven days notice of his expected time of arrival at CERA to "CADEQ EAVARY" who will maximate loading port(s) also "PRODIFFORS MOSCOT" and "SOVERACET MOSCOT". Septemb to telegraph "PRODIFFORS MOSCOT" and "SOVERACET MOSCOT" five days notice before expected arrival at discharging port.

Default under this clause shall not be considered as a breach of the Charter Party but 24 hours to be added to the time allowed for loading or discharging for each omission.

In case of vessel's delay Captain is obliged to inform Charterers accordingly.

Ceptain to telegraph to "SOVFRACET MOSCOU" the date of completion of discharging.

- 7. Charterers! liability shall cease as soon as the cargo is shipped; the Owners having a lien on the cargo for freight, deadfreight, desurrage and svarage.
- 6. 75% of total FREIGHT to be payable in British & Sterling in London and 25% through the Soviet-Pinnish obsaring agreement discountless and non-returnable ship and/or cargo lost or not lost as follows:- 50% (fifty per cent) prepaid within 5 days after signing Bills of Leding, 40% of freight on right and trush delivery of the cargo, and 10% of freight on receiving from the Centers the final freight account with supporting vouchers.
- 9. ARRITRATION CLAUSE. Any dispute arrive under this Charter Party shall be referred to arbitration (Arbitrator to be nominated by the Owners and the other by the Charterers. To case such Arbitrators cannot agree, then the dispute to be referred to the decision of an Unpire, the shall be appointed by the said Arbitrators.

 On request of Owners a guarantee letter to be signed by or on behalf of Charterers or by their Bankers, in which case lien on the eargo not to be exercised by Owners.
- of a strike or lock-out of any class of wormen essential to the loading and/or discharging of the cargo time for loading and/or discharging shall not count during the continuation of such strike or lock-out and in case of any delay by reason of the aforementioned causes, no claim for damages shall be made by the Shippers, the Consigness of the cargo, the Owners of the ship or by any other party under this Charter.
- 11. Cargo to be so loaded and discharged as to leave vessel in seaworthy trim to shift between ports, Master being responsible for same.

Declassified in Part - Sanitized Copy Approved for Release 2012/06/04 : CIA-RDP81-00280R000100100002-1 50X1-HUM

